



CXone Mpower EXPERT

Eシリーズファンが取り外されました

https://kb-ja-stage.netapp.com/on-prem/E-series/Hardware-KBs/E-Series_Fan_Status_is_Removed

Updated: Wed, 22 Apr 2026 00:45:37 GMT

環境

- Eシリーズシステム
- DE460C

問題

- Recovery Guruで次のアラートが報告されます。

Failure Entry 2: **SM_REMOVED_SUPPORT_CRU_FAN-Recovery Failure Type Code: 88**

Storage array: XXXXXXXXX

Component reporting problem: Fan canister (Right) Status: Removed

Location: Controller/Drive shelf 99

Component requiring service: Fan canister Service action (removal) allowed: Already removed End of Failure Entry 2: Back to top

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- ファンキャニスターを取り付け直しても問題が維持される