



NiCE

E5760 ファンの一時的なエラー

https://kb-ja-stage.netapp.com/on-prem/E-series/Hardware-KBs/E5760_FAN_temporary_error

Updated: Wed, 13 May 2026 07:44:53 GMT

環境

E5760

問題

- コントローラAのリブート後にファンエラーが検出されましたが、あとで自動的にリカバリされます。
- メジャーイベントログの例

```
A:2/15/23, 7:41:27 PM (19:41:27) 238 2606 Start-of-day routine begun - Shelf 99, Bay A
```

```
A:2/15/23, 3:50:55 AM (03:50:55) 235 2809 Controller shelf component changed to optimal - Shelf 99, Fan canister 1, Bay 2
```

```
A:2/15/23, 3:50:55 AM (03:50:55) 234 2809 Controller shelf component changed to optimal - None
```

```
B:2/15/23, 3:51:02 AM (03:51:02) 233 2809 Controller shelf component changed to optimal - Shelf 99, Fan canister 1, Bay 2
```

```
B:2/15/23, 3:51:02 AM (03:51:02) 232 2809 Controller shelf component changed to optimal - None
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

A:2/15/23, 3:09:13 AM (03:09:13) 42 280b Controller shelf component failed - Shelf 99, Fan canister 1, Bay 2 <--CRITICAL

A:2/15/23, 3:08:03 AM (03:08:03) 35 2606 Start-of-day routine begun - Shelf 99, Bay A